

**Photograph 1**  
**Existing COIC/LNFH Shared Diversion Facilities on Icicle Creek**



**Photograph 2**  
**Debris Rack at Inlet to Diversion Pipeline under Control House**



**Photograph 3**  
**Inside Control House with Control Gate Operator**



**Photograph 4**  
**Bifurcation, Valve Enclosure**



**Photograph 5**  
**Inside Valve Enclosure**



**Photograph 6**  
**Bifurcation with Fish Bypass Pipe and Fish Screen**



**Photograph 7**  
**Fish Screen and Paddle Wheel**



**Photograph 8**  
**Weir, Pipe Inlet, Debris Rack**



**Photograph 9**  
**Pipe through RV Campground on Icicle Road**



**Photograph 10**  
**Open Ditch Downstream of Pipe Outlet at Sleeping Lady**



**Photograph 11**  
**Open Ditch West of Icicle Road**



**Photograph 12**  
**Open Ditch West of Icicle Road**



**Photograph 13**  
**Culvert Crossing at Icicle Road**



**Photograph 14**  
**Culvert Crossing at Shore Street**



**Photograph 15**  
**Typical Turnout Structure West of Icicle Road**



**Photograph 16**  
**Typical Pumped Turnout West of Icicle Road**





**Photograph 17**  
**Lateral Intake Structure West of Icicle Road**



**Photograph 18**  
**Lateral Intake Structure West of Icicle Road**



**Photograph 19**  
**Inlet to Tailwater Pipeline**



**Photograph 20**  
**Tailwater Location on Wenatchee River**



**Photograph 21**  
**Proposed Intake Location on Icicle Creek**



**Photograph 22**  
**Proposed Intake Location from Top of Bank Looking East Across Icicle Creek**



**Photograph 23**  
**Proposed Pump Station Location at East End of Shore Street**

